



# GLOBALINS

INTERNATIONAL SURVEYING & EXPERTIZING COMPANY



Location: Poti, Georgia	Office: <b>GLOBALINS</b> Georgia	Client: <b>Moulds And Metals Georgia Limited</b>
Poti port, berth No:5	9 April Avenue 22 F. 23, Poti 4400, Georgia Tel. : + 995 493270001	
Inspection Product:  Steel billets	Inspector(s) : Z.Naroushvili,G.Kvetenadze T.Skhulukhia, G.Khvichia	Date:  29.05.2019

## INSPECTION REPORT

No. M 009/2019

### TIME LOG

<i>DESCRIPTION</i>	<i>TIME</i>	<i>DATE</i>
Inspectors arrived at the place of inspection	22:00	28.05.2019
Loading commenced	22:30	28.05.2019
Loading completed	15:00	29.05.2019
Inspectors left	15:15	29.05.2019

## Inspection Report

**In pursuance of an order received from our Principal:** Moulds And Metals Georgia Limited

**To carry out inspection summarized as:** Inspection of cargo during loading operation

**Of a consignment designated as:** Steel billets

**Place of inspection:** Poti port, berth No: 5, Poti, Georgia

**Date of inspection:** According to the above Time log

-----

This is to confirm that the undersigned surveyor at the request of **Moulds And Metals Georgia Limited**, we did on board the vessel "TUZLA" whilst berthed at Pot port, berth No: 5 on 28 of May 2019 for the purpose of conducting the following surveys:

To attend the loading operations of the Steel Billets into the vessel's cargo holds, carry out tallying, weighing and to ensure that the loading operation is carried out in a safe and efficient manner.

To inspect the consignment on completion of loading operations and to ascertain it's condition and to ensure that the goods were adequately secured for the intended voyage from Poti to its final destination at Diliskelesi / Turkey.

This report covers the condition, tallying and weighing of 5777 pieces (844 bundles) of Steel Billets for shipper concern on board the vessel "TUZLA".

The shipment of 5777 pieces (844 bundles) of Steel Billets were safely loaded on board of the vessel "TUZLA" and the unit ware adequately secured for the intended voyage from Poti to Diliskelesi / Turkey.

### General Information

Consignee	EPAŞ HADDECİLİK SAN. VE TİC. A.Ş.
Shipper	Moulds and Metals Georgia Limited
Description of cargo	Steel Billets

In addition to the undersigned, the following personnel were also in attendance:

Mr. Hasan Ali Ugur	:	Master of the MV "TUZLA" for and on behalf of the Owners / Operators of the vessel.
Mr. Hasan Firket Ergun	:	Chief Officer of the MV "TUZLA" for and on behalf of the Owners / Operators of the vessel.

**Particular of Vessel:**

Name of vessel	"TUZLA"	Port of Registry	COOK ISLAND
IMO No.	7920364	Call sign	E5U2644
GRT	2485.00 ton	NRT	1463.00 ton
LOA	86.14 m	LBP	75.00 m
Breadth	14.00 m	Depth	7.90 m

**INSPECTION**

Prior to loading operation, we boarded the vessel "TUZLA" whilst she was safely berthed at Poti port berth No: 5 we met with the vessel's Master, Chief Officer and follow by a brief discussion on the sequence of the loading operation to be carried out.

The 5777 pieces (844 bundles) of Steel Billets were adequately lashed, all the lashing and separation materials used were noted to be in good condition and suitable for the securing purposes.

**QUANTITY**

Tallying was performed during whole loading period of goods to the vessel together with ship's and port's tallyman. According to the tallying result established that 5777 pieces (844 bundles) of Steel Billets were loaded into vessel's holds.

**WEIGHT**

The weight of cargo was established by scaling of trucks while transporting goods beside the ship. All loaded and empty trucks were scaled in our presence and total loaded quantity established to be 4008.180 mts.

**LOADING PLAN**

The goods were stowed and secured as follows:

Position	Number of Billets	Number of Bundles	Weight (mt)
Hold No: 1	5777	844	4008.180

# PHOTO REPORT

Photo No.1



Photo No.2



Photo No.3




Photo No.4




Photo No.5




Photo No.6




Photo No.7



Photo No.8




Photo No.9





Photo No.10



*THIS REPORT REFLECTS OUR FINDINGS AT THE TIME AND PLACE OF INSPECTION AND IT WAS CARRIED OUT TO THE BEST OF OUR ABILITY AND KNOWLEDGE AND WITHOUT ANY PREJUDICE TO THE PARTIES CONCERNED.*

*This report is signed and dated in Poti on 29/05/2019 for and on behalf of GLOBALINS Georgia Ltd*

